









Highbay1 1/21



Seilabhängung / Rope Suspension

59HL92004
59HL92005










2a 51HL ... 1 .






2b 51HL ... 2 .






2c 51HL ... 3 .






2d 5 . HN ... A...




2e 5 . HN ... B...










Siteco GmbH
Georg-Simon-Ohm-Straße 50
83301 Traunreut, Germany
mail: technicalsupport@siteco.de
Phone: +49 8669 / 33-844
www.siteco.com



5MA39-255154_ag
19.09.2024 / SCH