


# Highbay 11 Xtreme Highbay 11 / 21

## Kettenabhängung / Chain Suspension

59HL92001

59HL92002




**siteco**

59HL92001




**kg** = 0.55

59HL92002




**kg** = 0.55

1a 59HL92001




1b 59HL92002


[ mm ]




**2a** 5XA779 . 2.../51HF .. DB...




59HL92001




59HL92002




**2b** 5XA779 . 1.../5HF .. DA...






59HL92001






59HL92002








**2c 51HL ... 1 .**






**2d 51HL ... 2 .**






2e 51HL ... 3.






**2f** 5 . HN ... A...



**2g** 5 . HN ... B...







Siteco GmbH  
Georg-Simon-Ohm-Straße 50  
83301 Traunreut, Germany  
mail: [technicalsupport@siteco.de](mailto:technicalsupport@siteco.de)  
Phone: +49 8669 / 33-844  
[www.siteco.com](http://www.siteco.com)



5MA39-255153\_aj  
19.09.2024 / SCH